



max.
25W




Soldering - Solderen - Soudage - Lötén - Soldadura - Lödning - Juottami nen - Saldatura - Solda

<p>1 1003: R1, R2, R3 4700: R4, ..., R9</p>	<p>2 LD1, ..., LD7</p>
<p>3 T1, T2, T3</p>	<p>4 C1, ..., C4</p>
<p>5 </p>	<p>6 </p>

7

8



Assembly - Montage - Bouw - Zusammenbau - Montaje -
assemblaggio - montagem - monterng



Search for "Velleman MK183 assembly"